

# **TS27R tool setting probe**



www.renishaw.com/ts27r

#### Specification

Principal application		Tool measuring and broken tool detection on all sizes of vertical and horizontal
		machining centres and all gantry machining centres.
Transmission type		Hard-wired transmission
Compatible interfaces		MI 8-4, HSI or HSI-C
Recommended styli		Disc stylus (tungsten carbide, 75 Rockwell C) or
		Square tip stylus (ceramic tip, 75 Rockwell C)
Weight with disc stylus		1055 g (37.21 oz)
Cable (to interface)	Specification	Ø4.4 mm (0.17 in), 4-core screened cable, each core $7\times0.2$ mm
	Length	10 m (32.8 ft)
	Electrical	Cable on the end of unit
	Connection	
Sense directions		±X, ±Y, +Z
Unidirectional repeatability		1.00 μm (40 μin) 2σ (see note 1)
Stylus trigger force		1.30 N to 2.40 N, 133 gf to 245 gf (4.68 ozf to 8.63 ozf) depending on sense direction
(see notes 2 and 3)		
Sealing		IPX8, BS EN 60529:1992+A2:2013 (IEC 60529:1989+A1:1999+A2:2013)
Mounting		M12 (1/2 in) T bolt (not supplied)
		Optional Spirol pins to allow accurate remounting
Operating temperature		+5 °C to +60 °C (+41 °F to 140 °F)

Note 1 Performance specification is tested at a standard test velocity of 480 mm/min (18.9 in/min) with a 35 mm stylus. Significantly higher velocity is possible depending on application requirements.

Note 2 Trigger force, which is critical in some applications, is the force exerted on the component by the stylus when the probe triggers. The maximum force applied will occur after the trigger point (overtravel). The force value depends on related variables including measuring speed and machine deceleration.

Note 3 These are the factory settings; manual adjustment is not possible.

For further information, and the best possible application and performance support, please contact Renishaw or visit www.renishaw.com/ts27r

Renishaw plc


New Mills, Wotton-under-Edge Gloucestershire, GL12 8JR United Kingdom **T** +44 (0)1453 524524

**F** +44 (0)1453 524901 **E** uk@renishaw.com

www.renishaw.com



## **TS27R dimensions**



### Spare parts and accessories

A full range of spare parts and accessories is available. Please contact Renishaw for a full list.

#### For worldwide contact details, visit www.renishaw.com/contact

RENISHAW HAS MADE CONSIDERABLE EFFORTS TO ENSURE THE CONTENT OF THIS DOCUMENT IS CORRECT AT THE DATE OF PUBLICATION BUT MAKES NO WARRANTIES OR REPRESENTATIONS REGARDING THE CONTENT. RENISHAW EXCLUDES LIABILITY, HOWSOEVER ARISING, FOR ANY INACCURACIES IN THIS DOCUMENT.